

MOVE IN/OUT INSPECTION



123 Main St. Fort Myers, FL 33919

Inspected on September 14, 2018 12:32 PM

| Report Created on September 14, 2018 1:40 PM

Overview

Electric Account Number :	
---------------------------	--

General Information

Items	Values	Notes
# of Keys	2 House Keys	
# of Remotes	1 Garage Remote	

Entry

Items	Values	Notes
Doorbell	Good	
Front Door	Good	
Walls	Good	Seven pre-existing holes in the wall from pictures hanging.
Ceiling	Good	
Flooring	Good	

Living Room

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Window Coverings	Good	
Flooring	Good	

Items	Values	Notes
Baseboards	Good	
Lights	Good	
Ceiling Fan	Good	

Dining Room

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Flooring	Good	
Lights	Good	
Power Outlets	Good	

Kitchen

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Windows	Good	
Window Coverings	Good	
Flooring	Good	
Lights	Good	
Air Conditioning	Good	
Cabinets	Good	
Countertops	Good	
Pantry	Good	
Refrigerator	Good	
Stove Top	Good	
Sink / Faucet	Good	
Garbage Disposal	Good	
Microwave	Good	
Dishwasher	Good	

Bedroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Doors	Good	
Windows	Good	
Window Coverings	Good	
Flooring	Good	
Baseboards	Good	
Closet	Good	

Bathroom

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Windows	Good	
Window Coverings	Good	
Flooring	Good	
Lights	Good	
Cabinets	Good	
Countertop	Good	
Shower	Good	
Shower Door	Good	
Bath	Good	
Mirror	Good	
Sink	Good	
Tiling	Good	
Toilet Bowl	Good	

Bedroom 2

Items	Values	Notes
Walls	Good	
Ceiling	Good	

Items	Values	Notes
Doors	Good	
Windows	Good	
Flooring	Good	
Closet	Good	

Bedroom 3

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Windows	Good	
Flooring	Good	
Lights	Good	
Closet	Good	

Bathroom 2

Items	Values	Notes
Walls	Good	
Ceiling	Good	
Flooring	Good	
Lights	Good	
Cabinets	Good	
Towel Rack	Good	
Countertop	Good	
Shower	Good	
Bath	Good	
Mirror	Good	

Garage/Carport

Items	Values	Notes
Walls	Good	

Items	Values	Notes
Power Outlets	Good	
Garage Door	Good	

Mechanical

Items	Values	Notes
Water Heater	Good	
Air Conditioner	Good	
Washer	Good	
Dryer	Good	

Photos


Entry Photos




Front Door (1/3)
09/14/2018 4:32 PM



Front Door (2/3)
09/14/2018 4:32 PM



Front Door (3/3)
09/14/2018 4:32 PM




Walls (1/15)
09/14/2018 4:34 PM




Walls (2/15)
09/14/2018 4:34 PM



Walls (3/15)
09/14/2018 4:34 PM



Walls (4/15)
09/14/2018 4:34 PM




Walls (5/15)
09/14/2018 4:34 PM

Entry Photos




Walls (6/15)
09/14/2018 4:34 PM



Walls (7/15)
09/14/2018 4:34 PM



Walls (8/15)
09/14/2018 4:34 PM



Walls (9/15)
09/14/2018 4:34 PM



Walls (10/15)
09/14/2018 4:34 PM




Walls (11/15)
09/14/2018 4:34 PM



Walls (12/15)
09/14/2018 4:34 PM




Walls (13/15)
09/14/2018 4:34 PM



Walls (14/15)
09/14/2018 4:34 PM



Walls (15/15)
09/14/2018 4:34 PM



Ceiling
09/14/2018 4:33 PM

Living Room Photos



Walls (1/4)
09/14/2018 4:35 PM



Walls (2/4)
09/14/2018 4:35 PM



Walls (3/4)
09/14/2018 4:35 PM



Walls (4/4)
09/14/2018 4:35 PM




Ceiling (1/4)
09/14/2018 4:35 PM



Ceiling (2/4)
09/14/2018 4:35 PM



Ceiling (3/4)
09/14/2018 4:35 PM



Ceiling (4/4)
09/14/2018 4:35 PM



Window Coverings (1/4)
09/14/2018 4:35 PM



Window Coverings (2/4)
09/14/2018 4:35 PM



Window Coverings (3/4)
09/14/2018 4:35 PM



Window Coverings (4/4)
09/14/2018 4:35 PM



Flooring (1/4)
09/14/2018 4:35 PM



Flooring (2/4)
09/14/2018 4:35 PM



Flooring (3/4)
09/14/2018 4:35 PM



Flooring (4/4)
09/14/2018 4:36 PM

Living Room Photos



Ceiling Fan
09/14/2018 4:36 PM

Dining Room Photos



Walls (1/4)
09/14/2018 4:36 PM



Walls (2/4)
09/14/2018 4:36 PM



Walls (3/4)
09/14/2018 4:36 PM



Walls (4/4)
09/14/2018 4:36 PM



Flooring (1/2)
09/14/2018 4:36 PM



Flooring (2/2)
09/14/2018 4:36 PM



Lights
09/14/2018 4:36 PM


Kitchen Photos




Walls (1/6)
09/14/2018 4:36 PM




Walls (2/6)
09/14/2018 4:36 PM




Walls (3/6)
09/14/2018 4:36 PM




Walls (4/6)
09/14/2018 4:36 PM



Walls (5/6)
09/14/2018 4:36 PM




Walls (6/6)
09/14/2018 4:36 PM



Ceiling (1/5)
09/14/2018 4:37 PM




Ceiling (2/5)
09/14/2018 4:37 PM



Ceiling (3/5)
09/14/2018 4:37 PM



Ceiling (4/5)
09/14/2018 4:37 PM



Ceiling (5/5)
09/14/2018 4:37 PM



Windows (1/3)
09/14/2018 4:37 PM




Windows (2/3)
09/14/2018 4:37 PM



Windows (3/3)
09/14/2018 4:38 PM



Flooring (1/3)
09/14/2018 4:38 PM



Flooring (2/3)
09/14/2018 4:38 PM

Kitchen Photos



Flooring (3/3)
09/14/2018 4:38 PM



Cabinets (1/5)
09/14/2018 4:38 PM



Cabinets (2/5)
09/14/2018 4:38 PM



Cabinets (3/5)
09/14/2018 4:38 PM



Cabinets (4/5)
09/14/2018 4:38 PM



Cabinets (5/5)
09/14/2018 4:38 PM



Countertops (1/8)
09/14/2018 4:38 PM



Countertops (2/8)
09/14/2018 4:38 PM



Countertops (3/8)
09/14/2018 4:38 PM



Countertops (4/8)
09/14/2018 4:39 PM



Countertops (5/8)
09/14/2018 4:39 PM



Countertops (6/8)
09/14/2018 4:39 PM



Countertops (7/8)
09/14/2018 4:39 PM



Countertops (8/8)
09/14/2018 4:39 PM



Pantry (1/3)
09/14/2018 4:39 PM



Pantry (2/3)
09/14/2018 4:39 PM

Kitchen Photos



Pantry (3/3)
09/14/2018 4:39 PM



Refrigerator (1/7)
09/14/2018 4:39 PM



Refrigerator (2/7)
09/14/2018 4:39 PM



Refrigerator (3/7)
09/14/2018 4:39 PM



Refrigerator (4/7)
09/14/2018 4:39 PM



Refrigerator (5/7)
09/14/2018 4:40 PM



Refrigerator (6/7)
09/14/2018 4:40 PM



Refrigerator (7/7)
09/14/2018 4:40 PM



Stove Top (1/2)
09/14/2018 4:40 PM



Stove Top (2/2)
09/14/2018 4:40 PM



Sink / Faucet (1/3)
09/14/2018 4:40 PM



Sink / Faucet (2/3)
09/14/2018 4:40 PM



Sink / Faucet (3/3)
09/14/2018 4:41 PM



Microwave (1/2)
09/14/2018 4:41 PM



Microwave (2/2)
09/14/2018 4:41 PM



Dishwasher (1/3)
09/14/2018 4:41 PM

Kitchen Photos



Dishwasher (2/3)
09/14/2018 4:41 PM



Dishwasher (3/3)
09/14/2018 4:41 PM

Bedroom Photos



Walls (1/4)
09/14/2018 4:43 PM




Walls (2/4)
09/14/2018 4:43 PM




Walls (3/4)
09/14/2018 4:43 PM




Walls (4/4)
09/14/2018 4:44 PM




Ceiling (1/4)
09/14/2018 4:45 PM



Ceiling (2/4)
09/14/2018 4:45 PM



Ceiling (3/4)
09/14/2018 4:45 PM




Ceiling (4/4)
09/14/2018 4:45 PM



Windows (1/2)
09/14/2018 4:46 PM



Windows (2/2)
09/14/2018 4:46 PM



Flooring (1/4)
09/14/2018 4:46 PM




Flooring (2/4)
09/14/2018 4:46 PM

Bedroom Photos



Flooring (3/4)
09/14/2018 4:46 PM



Flooring (4/4)
09/14/2018 4:46 PM




Lights
09/14/2018 4:46 PM



Closet (1/12)
09/14/2018 4:46 PM



Closet (2/12)
09/14/2018 4:46 PM



Closet (3/12)
09/14/2018 4:46 PM



Closet (4/12)
09/14/2018 4:46 PM



Closet (5/12)
09/14/2018 4:46 PM



Closet (6/12)
09/14/2018 4:47 PM



Closet (7/12)
09/14/2018 4:47 PM



Closet (8/12)
09/14/2018 4:47 PM




Closet (9/12)
09/14/2018 4:47 PM



Closet (10/12)
09/14/2018 4:47 PM



Closet (11/12)
09/14/2018 4:47 PM



Closet (12/12)
09/14/2018 4:47 PM

Bathroom Photos



Walls (1/11)
09/14/2018 4:47 PM



Walls (2/11)
09/14/2018 4:47 PM



Walls (3/11)
09/14/2018 4:47 PM



Walls (4/11)
09/14/2018 4:47 PM



Walls (5/11)
09/14/2018 4:47 PM




Walls (6/11)
09/14/2018 4:47 PM



Walls (7/11)
09/14/2018 4:47 PM



Walls (8/11)
09/14/2018 4:47 PM




Walls (9/11)
09/14/2018 4:47 PM




Walls (10/11)
09/14/2018 4:47 PM




Walls (11/11)
09/14/2018 4:48 PM



Ceiling (1/3)
09/14/2018 4:48 PM



Ceiling (2/3)
09/14/2018 4:48 PM



Ceiling (3/3)
09/14/2018 4:48 PM




Windows (1/2)
09/14/2018 4:48 PM



Windows (2/2)
09/14/2018 4:48 PM


Bathroom Photos




Flooring (1/4)
09/14/2018 4:48 PM



Flooring (2/4)
09/14/2018 4:48 PM




Flooring (3/4)
09/14/2018 4:48 PM




Flooring (4/4)
09/14/2018 4:48 PM




Lights (1/5)
09/14/2018 4:48 PM



Lights (2/5)
09/14/2018 4:48 PM



Lights (3/5)
09/14/2018 4:48 PM



Lights (4/5)
09/14/2018 4:49 PM



Lights (5/5)
09/14/2018 4:49 PM



Cabinets (1/5)
09/14/2018 4:49 PM




Cabinets (2/5)
09/14/2018 4:49 PM



Cabinets (3/5)
09/14/2018 4:49 PM



Cabinets (4/5)
09/14/2018 4:49 PM



Cabinets (5/5)
09/14/2018 4:49 PM



Countertop (1/6)
09/14/2018 4:49 PM



Countertop (2/6)
09/14/2018 4:49 PM


Bathroom Photos




Countertop (3/6)
09/14/2018 4:49 PM



Countertop (4/6)
09/14/2018 4:49 PM



Countertop (5/6)
09/14/2018 4:49 PM



Countertop (6/6)
09/14/2018 4:49 PM




Shower (1/7)
09/14/2018 4:51 PM



Shower (2/7)
09/14/2018 4:51 PM



Shower (3/7)
09/14/2018 4:51 PM




Shower (4/7)
09/14/2018 4:51 PM



Shower (5/7)
09/14/2018 4:51 PM



Shower (6/7)
09/14/2018 4:51 PM




Shower (7/7)
09/14/2018 4:51 PM



Bath (1/4)
09/14/2018 4:51 PM



Bath (2/4)
09/14/2018 4:51 PM



Bath (3/4)
09/14/2018 4:51 PM



Bath (4/4)
09/14/2018 4:51 PM



Mirror (1/3)
09/14/2018 4:52 PM


Bathroom Photos



Mirror (2/3)
09/14/2018 4:52 PM



Mirror (3/3)
09/14/2018 4:52 PM



Sink (1/4)
09/14/2018 4:52 PM



Sink (2/4)
09/14/2018 4:52 PM



Sink (3/4)
09/14/2018 4:52 PM




Sink (4/4)
09/14/2018 4:52 PM



Toilet Bowl
09/14/2018 4:53 PM

Bedroom 2 Photos




Walls (1/4)
09/14/2018 4:54 PM



Walls (2/4)
09/14/2018 4:54 PM




Walls (3/4)
09/14/2018 4:54 PM




Walls (4/4)
09/14/2018 4:54 PM




Ceiling (1/3)
09/14/2018 4:54 PM



Ceiling (2/3)
09/14/2018 4:54 PM



Ceiling (3/3)
09/14/2018 4:54 PM



Flooring (1/4)
09/14/2018 4:55 PM


Bedroom 2 Photos



Flooring (2/4)
09/14/2018 4:55 PM



Flooring (3/4)
09/14/2018 4:55 PM



Flooring (4/4)
09/14/2018 4:55 PM



Closet (1/4)
09/14/2018 4:55 PM



Closet (2/4)
09/14/2018 4:55 PM




Closet (3/4)
09/14/2018 4:56 PM



Closet (4/4)
09/14/2018 4:56 PM


Bedroom 3 Photos



Walls (1/7)
09/14/2018 4:56 PM




Walls (2/7)
09/14/2018 4:56 PM



Walls (3/7)
09/14/2018 4:56 PM




Walls (4/7)
09/14/2018 4:56 PM




Walls (5/7)
09/14/2018 4:56 PM



Walls (6/7)
09/14/2018 4:56 PM



Walls (7/7)
09/14/2018 4:56 PM




Ceiling (1/3)
09/14/2018 4:56 PM

Bedroom 3 Photos




Ceiling (2/3)
09/14/2018 4:56 PM



Ceiling (3/3)
09/14/2018 4:56 PM



Windows
09/14/2018 4:56 PM



Flooring (1/3)
09/14/2018 4:56 PM



Flooring (2/3)
09/14/2018 4:57 PM



Flooring (3/3)
09/14/2018 4:57 PM



Closet (1/2)
09/14/2018 4:57 PM




Closet (2/2)
09/14/2018 4:57 PM


Bathroom 2 Photos



Walls (1/12)
09/14/2018 4:57 PM




Walls (2/12)
09/14/2018 4:57 PM




Walls (3/12)
09/14/2018 4:57 PM



Walls (4/12)
09/14/2018 4:57 PM



Walls (5/12)
09/14/2018 4:57 PM



Walls (6/12)
09/14/2018 4:57 PM



Walls (7/12)
09/14/2018 4:57 PM



Walls (8/12)
09/14/2018 4:58 PM

Bathroom 2 Photos



Walls (9/12)
09/14/2018 4:58 PM



Walls (10/12)
09/14/2018 4:58 PM



Walls (11/12)
09/14/2018 4:58 PM



Walls (12/12)
09/14/2018 4:58 PM

Garage/Carport Photos



Walls (1/8)
09/14/2018 5:03 PM



Walls (2/8)
09/14/2018 5:03 PM



Walls (3/8)
09/14/2018 5:03 PM



Walls (4/8)
09/14/2018 5:03 PM



Walls (5/8)
09/14/2018 5:03 PM



Walls (6/8)
09/14/2018 5:03 PM



Walls (7/8)
09/14/2018 5:03 PM



Walls (8/8)
09/14/2018 5:03 PM

Mechanical Photos



Washer (1/2)
09/14/2018 5:04 PM



Washer (2/2)
09/14/2018 5:04 PM



Pool (1/10)
09/14/2018 5:01 PM



Pool (2/10)
09/14/2018 5:01 PM



Pool (3/10)
09/14/2018 5:01 PM



Pool (4/10)
09/14/2018 5:01 PM



Pool (5/10)
09/14/2018 5:01 PM



Pool (6/10)
09/14/2018 5:01 PM




Pool (7/10)
09/14/2018 5:01 PM



Pool (8/10)
09/14/2018 5:01 PM



Pool (9/10)
09/14/2018 5:01 PM



Pool (10/10)
09/14/2018 5:01 PM